


PROCEDURE

1.INSPECT NO. 1 CHAIN TENSIONER SUB-ASSEMBLY

a.




*a	Raise
*b	Move
*c	Lock

Check that the plunger moves smoothly when the ratchet pawl is raised with your finger.

- b. Release the ratchet pawl, then check that the plunger is locked in place by the ratchet pawl and does not move when pushed with your finger.

2.INSPECT CHAIN SUB-ASSEMBLY

a.



*a	Measurement Length
----	--------------------

Pull the chain sub-assembly with a force of 140 N (14 kgf, 31.5 lbf) as shown in the illustration.


- b. Using a vernier caliper, measure the length of 15 links.

Maximum Chain Elongation:
122.6 mm (4.827 in.)

NOTICE:
Perform the measurement at 3 random places. Use the average of the measurements.

If the average elongation is greater than the maximum, replace the chain sub-assembly.

3.INSPECT CAMSHAFT TIMING GEAR OR SPROCKET



Place the chain sub-assembly around the camshaft timing gear or sprocket.


- b. Using a vernier caliper, measure the diameter of the camshaft timing gear or sprocket and chain sub-assembly.
Minimum Gear Diameter (with Chain):
97.3 mm (3.831 in.)

NOTICE:

The vernier caliper must be in contact with the chain rollers when measuring.

If the diameter is less than the minimum, replace the chain sub-assembly and camshaft timing gear or sprocket.

4.INSPECT CRANKSHAFT TIMING SPROCKET



Place the chain sub-assembly around the crankshaft timing sprocket.


- b. Using a vernier caliper, measure the diameter of the crankshaft timing sprocket and chain sub-assembly.
Minimum Gear Diameter (with Chain):
51.6 mm (2.032 in.)

NOTICE:

The vernier caliper must be in contact with the chain rollers when measuring.

If the diameter is less than the minimum, replace the chain sub-assembly and crankshaft timing sprocket.

5.INSPECT CHAIN TENSIONER SLIPPER




Using a vernier caliper, measure the chain tensioner slipper wear.

Maximum Wear:
1.0 mm (0.0394 in.)

If the wear is greater than the maximum, replace the chain tensioner slipper.

6.INSPECT NO. 1 CHAIN VIBRATION DAMPER

a.




Using a vernier caliper, measure the No. 1 chain vibration damper wear.

Maximum Wear:
1.0 mm (0.0394 in.)

If the wear is greater than the maximum, replace the No. 1 chain vibration damper.

7.INSPECT CYLINDER HEAD SET BOLT

a.



Using a vernier caliper, measure the length of the cylinder head set bolt from the seat to the end.

Standard Length:
156.0 to 159.0 mm (6.142 to 6.260 in.)


Maximum Length:
159.5 mm (6.280 in.)

HINT:

- If the length is greater than the maximum, replace the cylinder head set bolt with a new one. Failure to do so may lead to engine damage.
- If there is any thread deformation, replace the cylinder head set bolt with a new one.

8.INSPECT CAMSHAFT

a.




Inspect the camshaft for runout.

- Place the camshaft on V-blocks.
- Using a dial indicator, measure the runout at the center journal.

**Maximum Runout:
0.03 mm (0.00118 in.)**

If the runout is greater than the maximum, replace the camshaft.

b.



Inspect the cam lobes.

- i. Using a micrometer, measure the cam lobe height.
If the cam lobe height is less than the minimum, replace the camshaft.

Standard Cam Lobe Height:


Intake:

44.333 to 44.433 mm (1.7454 to 1.7493 in.)

Exhaust:

43.761 to 43.861 mm (1.7229 to 1.7268in.)

c.



Inspect the camshaft journals.

- i. Using a micrometer, measure the journal diameter.

Standard Journal Diameter:

Journal Position	Specified Condition
No. 1	34.449 to 34.465 mm (1.35626 to 1.35689 in.)
Other	22.949 to 22.965 mm (0.90350 to 0.90413 in.)


If the journal diameter is not as specified, check the oil clearance.

[Click here](#)Engine / Hybrid System>1ZZ-FE ENGINE MECHANICAL>CYLINDER HEAD>INSPECTION



9.INSPECT EXHAUST MANIFOLD

a.



Using a precision straightedge and feeler gauge, measure the warpage on the contact surface of the cylinder head sub-assembly.

Maximum Warpage:
0.7 mm (0.0276 in.)

If the warpage is greater than the maximum, replace the exhaust manifold.